

Phase 1

STEP 1: LIST

WMU will review the Clark County Health Department & Water Service Records to prepare a list of FSEs.

STEP 2: TV SEWER INSPECTION AND PERMIT APPLICATION

WMU will conduct TV sewer inspections and assist FSEs with completion of their FOG Permit Application.

STEP 3: APPLICATION EVALUATION

WMU will determine if FSE is eligible for permit or a permit exemption and assign a risk ranking.

- Develop specifications and design standards for FOG Control devices
- Develop protocols for permitting, monitoring, inspections, reporting

Phase 2

STEP 4: PERMIT

WMU will issue a FOG Control Permit or permit exemption letter.

STEP 5: COMPLIANCE

Through onsite inspections, monitoring and reporting, WMU will monitor FSE permit compliance.

If Non-compliant

STEP 6: ENFORCEMENT

WMU will follow the FOG Control Enforcement Response Guide.